

Format II

Action taken report for safety measures complied for the accidents occurred

Name of Company: BSES YAMUNA POWER LTD, NEW DELHI
Period of Report: Jan’2026

Year: 2026

Sl. No.	Location Of Accident and Details Of Victim	Date of occurrence	Type of accident	Cause of accident	Findings of CEI/EI/AEI	Remedies suggested by CEI/EI/AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such accidents	Amount paid as compensation
1	A no supply complaint was received at 12:11 AM. On-site inspection revealed that sewer digging work by SKV School had damaged a 4*300 sqmm LT cable belonging to BYPL. As per local residents, a laborer suffered a flash injury during the incident.	06.04.2025	Public (Non-Fatal)	Based on site inspection, probable cause is Interference with BYPL network	Report awaited	Will be taken based on EI report if applicable.	NA, as report from EI is awaited	NA	NA
2	"Current leakage complaint received through IOMS and assigned to Yogender(Linemen)at 03:26PM.Both supply was disconnected from A-2 pocket and PWD street light from A-1 Pocket mayur Vihar phase-3 respectively on 03:48 PM dated 09/08/2025. People present on the spot told lineman that a man who is around 40 years old fainted while he was going in the water. "	09.08.2025	Public (Fatal)	Based on site inspection, probable cause is unknown	Report awaited	Will be taken based on EI report if applicable.	NA, as report from EI is awaited	NA	NA
3	While attending a PCR call, it came to notice that cable operator person got burnt when he touched live CT/PT unit at Ram Mohalla DP when tightening his network wire.	12.08.2025	Public (Fatal)	Based on site inspection, probable cause is Interference with BYPL network	Report awaited	Will be taken based on EI report if applicable.	NA, as report from EI is awaited	NA	NA
4	On 20th August 2025 at 14:49 Hrs, 400 KV Harsh Vihar – 66 KV Nand Nagri Ckt 1 tripped (Breakdown ID: B20082500014). Later, Smt. Pooja was electrocuted on the rooftop of a nearby building at Sunder Nagri due to low clearance (<1 m) from the 66 KV line. She sustained 60–70% burns and head injury (non-fatal) and is under treatment at GTB Hospital. The building violated CERC/DERC safety norms	20.08.2025	Public (Non-Fatal)	Based on site inspection, probable cause is Interference with BYPL network	Report awaited	Will be taken based on EI report if applicable.	NA, as report from EI is awaited	NA	NA
5	Electrocution of 3 nos. cows from street light pole at central verge road below pink line metro viaduct pillar no. 10, opposite karkardooma village, Delhi	29.08.2025	Animal (Fatal)	Based on site inspection, probable cause is unknown	Report awaited	Will be taken based on EI report if applicable.	NA, as report from EI is awaited	NA	NA

(Signature of the Licensee)