

DELHI ELECTRICITY REGULATORY COMMISSION

Viniyamak Bhawan, 'C' Block, Shivalik, Malviya Nagar, New Delhi- 110017.

No. F.11(463)/DERC/2008-09/

Petition No. 69/2008

In the matter of : Endangering the Regional Grid Security by continuous violation of
Section 24.1-24.3 of Delhi Electricity Grid Code:

The General Manager,
State Load Despatch Center (SLDC),
SLDC Building,
33Kv Grid Sub-Station,
Minto Road, New Delhi 110 002

.....**Petitioner**

VERSUS

1. BSES Rajdhani Power Limited
Through its : **CEO**
BSES Bhawan, Nehru Place,
New Delhi-110019.
2. BSES Yamuna Power Ltd.
Through its: **CEO**
Shakti Kiran Building,
Karkardooma
New Delhi – 110 092.
3. North Delhi Power Ltd.
Through its: **Managing Director**
Sub Station Building,
Hudson Lane,
Delhi 110 009,
4. The Secretary
New Delhi Municipal Council
Palika Kendra, Sansad Marg
New Delhi 100 001
5. Chief Engineer (Utilities)
CWE, MES, Kotwali Road,
Delhi Cantt,
New Delhi 110 010

...**Respondents.**

Coram :

**Sh. P.D. Sudhakar, Chairman, Sh. Shyam Wadhera, Member,
& Sh. J.P. Singh, Member**

Appearance :

1. Mr. Roop Kumar, GM, SLDC
2. Mr. V.Venugopal, DGM(SO) SLDC
3. Mr. Sanjeev Kumar A.M. (SO) SLDC
4. Mr. Prem Prakash, GM DTL
5. Mr. S.S. Sondhi, Asstt. Vice President, BRPL
6. Mr. Ajay Kumar, Addl. Mgr. BRPL
7. Mr. Mukesh Dadhich, DGM (SO) BYPL
8. Mr. Ashish Kumar Dutta, AGM, NDPL
9. Mr. Chamanlal, EE(E), NDMC

ORDER

(Date of Hearing 24.10.2011)
(Date of Order 17.01.2012)

1. Mr. S.S. Sondhi, Asstt. Vice President, BRPL, submitted that they have installed under frequency relays in their area of supply.
2. Mr. Mukesh Dadhich, DGM (SO) BYPL confirmed that they have also installed under frequency relays in their area of supply.
3. Mr. Ashish Kumar Dutta, AGM, NDPL, reiterated that NDPL has already installed under Frequency Relays in their area of supply and these under frequency relays have been put to service.
4. On the query of the Commission BRPL & BYPL confirmed that they have installed under frequency relays in their respective area of supply but these under frequency relays have not been put to service.
5. Mr. V.Venugopal, DGM(SO) SLDC, confirmed that BRPL & BYPL have installed under frequency relays in their respective areas of supply but these under frequency relays have yet to be put to service.
6. The Commission heard BRPL, BYPL, NDPL & SLDC at length. The Commission directs DISCOMs to put under frequency relays in their respective area of supply in service latest by 31.03.2012 and compliance of this direction of the Commission should also be reported to the Commission latest by 07.04.2012.
7. Accordingly, the Petition is disposed off.
8. Ordered accordingly.

Sd/-
(J.P. Singh)
Member

Sd/-
(Shyam Wadhera)
Member

Sd/-
(P.D. Sudhakar)
Chairman