

Format II

Action taken report for safety measures complied for the accidents occurred

Name of Company: BSES YAMUNA POWER LTD, NEW DELHI
Period of Report: APRIL 2019
Year: 2019

SI N o.	Locatio n of acciden t and details of victim	Date of occurre nce	Type of accide nt	Cause of accide nt	Findin gs of CEI/EI /AEI	Remedi es sugges ted by CEI/EI /AEI in various cases	Whethe r the remedy sugges ted is comple d	Action taken to avoid recurre nce of such accide nts	Amount paid as compen sa tion
1	66 KV Gazipur Gantry at Gazipur Dairy Farm Road. Victim: Unknown	28 April 19	Fatal	Electrocution while stealing the earthing strips meant for cable & structure earthing inside the gantry.	-	-	-	-	-

(Signature of the Licensee)

